

# Working with Schlenk Lines

- Wear appropriate PPE
  - Don't forget sensors when working with toxic gases
- Inspect all traps and o-rings before use
- Check all gas connections
  - Confirm identity of inlet gases
  - Check for leaks in vacuum and gas lines
- Evaluate using LN2 versus dry ice/isopropanol
- Never leave a vessel cooled using LN2 under static vacuum**